Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Construction of Bridge over Storm Water Drain at 12th Main Road. Mutyala Nagara in JP Park Ward No.17
2	Administration Approval & Date	JC/RRN/AS/2806/13-14 Dtd 18/01/2014 by JC (RRN)
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/290/13-14 Dtd:18/01/2014 by EE (RRND)
4	Estimate Amount	Rs.19.99 Lakhs
5	Job Code No.	017-14-000100
6	P-Code	P2434
7	Agreement No & date	EE/RRND/AG No./258/2013-14 Dtd.20-02-2014
8	Work order Number & Date	EE/RRND/W.O/258/2013-14 Dtd.20-02-2014
9	Contract Amount as per Agreement	Rs.20,88,142/-
10	Bill Amount	Rs.20,69,167/-
11	B.R. No. & Date	63/2015-16 dt.31-07-2015
12	Agency	M/s. J.C.Prakash
13	M.B. Number & Page No. of Measurement recordes	174/2013-14 Pages to 17363 to 17372
14	Date of Inspection	31-05-2016
15	Enclusures	1) Extract of MB No.174/13-14 Page 17373 2)4 Number of photos taken during inspection of above site.
16	Inspection Report	I have Inspected the above site along with the concerned person. The measurement of the Items which are suseptible for measurements have been checked and found to be Satisfactory

EE (RRND) RR Nagara

31/5/2016

(R.Sathyanarayana)
Inspection Report officer,

Scanned by CamScanner